

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name TV 70 wells

Site Address Lockhart

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J Font, DPAR, TAT, CKWAP, Geraghty & Miller,
SON/TECH, Ana Ramos (SSO)

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / Survey well conditions
before sampling

Findings, Accomplishments, and Results:

Cannot locate the well - No
record of it in office -

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

Will not sample - because EPA
Never sample it

Distribution:

Amy Chester - OKC -

259838



Site Inspection Report

Inspection Date(s) 8/22/90

Site Name

TUTU Wells Site

Site Address

FRANCIS

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, KWAN, TAT, DPWR, Blaght, & Miller,
Paul Tich, Anna Ramos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / Survey well conditions
before sampling

Findings, Accomplishments, and Results:

Working - left side casing could
be use for sample if need be.
Rt side work too.

2 individual wells - left side of Rd -
Rt side of Rd.

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No follow up work is needed
before sampling

Distribution:

Any cluster one

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name TJV well site

Site Address Dimitris

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, C. KWAN, TAT, DNR, Sarah Miller
DUI Tech, Anna Ranas

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / Survey well conditions before
sampling

Findings, Accomplishments, and Results:

Inside the shack, need to contact
owner to inspect. - But it
seems to be working

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

follow-up with site access.

Distribution:

Amey Chester one

Site Inspection Report

Inspection Date(s)

8/22/90

Site Name

TUTU Well site

Site Address

Senad alpha

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, CKWAP, TAT, DPNR, Glash 7 Miller,
port Tech, Anna Ramon

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect/Survey well conditions before
sampling

Findings, Accomplishments, and Results:

No problem - all in working order

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No work need to be done before
sampling

Distribution:

Amey Chester - OK

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name TUTU Wells etc

Site Address UTHA #1, #2, #3

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, C. KWAD, TAT, DPUR, Dargh Sheller
Soil Tech, Anna Rames.

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect/purvey well conditions before
pump

Findings, Accomplishments, and Results:

UTHA - need repair - no electrical
#1 power - might have to buy pump

#3 - working OK -

#2 - will not sample - because it is close
to #3

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

will need maintenance/repair
on UTHA #1 before sampling

Distribution:

Amy Christman

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name FUTS well site

Site Address Ramsley

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, CKWAN, JAT, DPNR, (Gentry)
Miller, Soil Tech, Ana Ramsley

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / survey well conditions before
sampling

Findings, Accomplishments, and Results:

Working -

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No further work is needed
before sampling

Distribution:

Wm. Chester - OK

Site Inspection Report

Inspection Date(s) 8/22/92

Site Name Rodriguez Auto - ESSO

Site Address 7070 Well Rd

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, CKW, DPR, TAT, Derych & Miller
for Tech, Ana Ramos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / survey well conditions before
sampling

Findings, Accomplishments, and Results:

working - has sampling value

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No further work is needed before
sampling

Distribution:

Amy Chester - OK

Site Inspection Report

Inspection Date(s) 8/21/83

Site Name

TOTO wells Site

Site Address

Smith

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

I. Fort, CKWAN, TAT, DPNR, Port Tech
DeVries, Miller, Anna Kanwa

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect/purvey well condition
before sampling

Findings, Accomplishments, and Results:

All in working order

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No follow-up maintenance
is needed before sampling

Distribution:

Amy Chotter - ONE

Site Inspection Report

Inspection Date(s) 8/21/90

Site Name TTU wells site

Site Address Derch

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Fort, C. KWAR, TAT, DPAR, Genzette
Miller, Soil Tech, Arc Ramon (ESSO)

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Survey / Inspect well condition before
sampling

Findings, Accomplishments, and Results:

No electrical power but has
pump - 16'6" to the table

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

need to send maintenance/repair
group before sampling

Distribution:

Amey Chester ORC

Site Inspection Report

Inspection Date(s) 8/21/90

Site Name Toto well site

Site Address Devcon #1, #2, #3

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

S. Font, DPRR, CKWAW, TAT, Blaght
Miller, Vol Tech, Ana Ramos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

inspect / survey well condition before
sampling.

Findings, Accomplishments, and Results:

All 3 wells are working -
but we will only sample

#1, #3, because #2

is next to #3 - it is hydrofractured
if we sample

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

No follow up work is needed
before sampling

Distribution:

Copy checker - OK

Site Inspection Report

Inspection Date(s) 8/21/90

Site Name Toto well site

Site Address Dede -

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, C. Kwau, TAT, DPWR, Alvin H. Miller, Jr.,
Paul Tech, Anne Ramos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect survey well condition before sampling

Findings, Accomplishments, and Results:

New owner - but well is working

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No additional work is needed
before sampling

Distribution:

Amey Chester - one

Site Inspection Report

Inspection Date(s) 9/20/90

Site Name Tutu Wells site

Site Address Hartman - Estate / Chester
Baker (Gassett)

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

CKWAB, J. Fort, J.M.H. TAT, G.M. 9 Doil Tech
Amy Ramos (ESS)

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / pump wells condition before
pump

Findings, Accomplishments, and Results:

H. Estate - Construction on site - But well is
connected and working

H. Chester - power disconnected - pump has not
been turned on.

Gassett - saw 2/3 wells - well pump the
one behind the building (looks like a
new well they installed)

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

Doil Tech will send maintenance/
repair team after receiving
the ~~access~~ access agreement

Distribution:

Amy Chester - one

Site Inspection Report

Inspection Date(s) 8/20/90

Site Name Tu Tu Well site

Site Address Farm lands Phipping PLANT
well # 1, # 2

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline Kwan, Joe Fort, Arnoldo Rodriguez
Dorothy Miller, Soil Tech & Anne Gloria Ramon
DPR - Julianne

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / survey drinking H₂O well for
sampling

Findings, Accomplishments, and Results:

well # 1 - power might be disconnect
2 looks like it's hooked up -
located in the west end of the
parking lot, near ESSO station -

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

Soil Tech will send a maintenance/
repair team to repair the
well before sampling start.

Distribution:

Amy Chesterton

Site Inspection Report

Inspection Date(s) 8/20/90

Site Name WV well site

Site Address Engle wells #1, #, #3

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline Kwan, Jose Fort, DPNR - Julie Mae
TNT, Miller, Seraphy, Pol/Tech, Anne Panos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

inspect / survey wells for future
sampling condition

Findings, Accomplishments, and Results:

- E#1 - immediately next to laundry - need
fitting for laundry purpose
E#2 - power seems to be disconnected -
need pump / electrical power
E#3 - OK

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

Pol Tech will send maintenance/
repair team after receiving site
access agreement from well owners

Distribution:

Amey cluster one

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name N70 site

Site Address Mathias

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

G. Font, E. Kwan, DNR, TAT, Geraghty & Miller,
DRI Tech, Anna Ramos (ESSO)

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / survey well condition
before sampling

Findings, Accomplishments, and Results:

Well is working

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No follow up work is
needed before sampling

Distribution:

Cmy Chester - OK

Site Inspection Report

Inspection Date(s) 8/20/90

Site Name 7070 wells site

Site Address Steel well

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Jose Font, CKwan, M, Park
Sul Tech 9, Berghy, Miller, Anna Kama

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / Purvey well ^{Condition} before
Sampling

Findings, Accomplishments, and Results:

Everything works

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

No repair / maintenance
Required

Distribution:

Amy Chofer

Site Inspection Report

Inspection Date(s) 8/21/90

Site Name

TW wells pit

Site Address

HARVEY well
found at O'Henry day Center
Building

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

John Fint, Caroline Kwan, TAT, DPRK
Bob Tech, Kerayth, Miller, Gene Kama

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Monitor / Inspection well before
shutting

Findings, Accomplishments, and Results:

Major Repair - well was damaged
No pipe - pump - Cap welded.

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Need to send Maurice /
Repair team before shutting

Distribution:

Army Chester

Site Inspection Report

Inspection Date(s) 8/22/90

Site Name TOTO well site

Site Address 711st

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

J. Font, DPOR, CKWAW, TAT, Soil Tech,
Shaughy Miller. Ana Gloria Ramos

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Inspect / Survey well conditions before
sampling

Findings, Accomplishments, and Results:

Working - high concentration of
BTEX, VOCs in the well area -
need modified Level C rules

a cistern sampling - the well also connects thru
to an apartment complex behind the
well house - approx 10 people

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State
officials, PRPs, or contractor regarding problems, schedule
for resolution, etc.)

Need to modify Rd access agreement
with well owner. - But no maintenance
work is needed before sampling

Distribution:

Am Chester one

Site Inspection Report

Inspection Date(s)

3/1/90

Site Name

Greene ESSO (A/C-WAY)

Site Address

Highway 30

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

SUSAN OSKITY, Caroline Kwan
DPRP-Evette, Clifford, Greg Rhymen, contractor-
MRT, PTT-HA

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Progress evaluation - of Air Stripper

Findings, Accomplishments, and Results:

Soil pit covered w/ PVC - wooden fenced -
treatment of soil have not started yet -
Recovery drain - Observed BTEX - odor

30-35 ft - Air stripper

the discharge to City sewerage -

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Distribution:

Site Inspection Report

Inspection Date(s) 3/1/90

Site Name TJTV - TEXACO

Site Address Highway 30 - East

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline K - EPA

Guy Rhynes - DPR

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Port pile - Progress evaluation -
104 @ follow-up

Findings, Accomplishments, and Results:

Port pile covered w/ PVC - observed vegetated grass
growing on sides of port pile - 3 feet wood
fence on 3 sides and metal pipe.
Venting system disconnected - observed personnel
in the port pile pulling grass.

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Await report on the port pile - Disposal
option -

Distribution:

Site Inspection Report

Inspection Date(s) 3/1/90

Site Name DeStop-ESSO -

Site Address Jet - 304

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline, Big, Clifford, Eric H. Pearson,
MRJ-HQ-UST CONTRACTORS

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Findings, Accomplishments, and Results:

Recovery-Air Stripper - WORKING
marsh holes all around the complex toward
Pola-Coca plant.
- potential 70 gpm - Air Stripper

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Add an additional recovery well
Need to look ambient effluent - Concentrator
Stripper over design - can handle 70 gpm.

Distribution:

Site Inspection Report
Inspection Date(s) 3/1/20

3/1/20

Site Name O'Henry Day Clarence Tr. Wash

Site Address East 38th Highway

Persons Conducting Inspection:

Persons conducting inspection:
(Identify EPA, State, Contractors, PRPs, Public, etc.)

Charlene Kwan - EPA

Greg Rhymen - DPR

Purpose of Inspection:

Purpose of inspection:
(Survey, data collection, field work, progress evaluation, etc.)

Survey, inspection -

Findings, Accomplishments, and Results:

Findings, Accomplishments, and Results:
Closed operation - wood fenced 3 sides and metal fence one side - Covered w/ PVC -
Vegetated cover growing - observed personnel inside the soil pile to pull vegetated out.

Follow-up and Recommendations:

Follow-up and Recommendations.
(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Distribution:

Site Inspection Report

Inspection Date(s) 2/27/90

Site Name Rodriguez - ESSO - TTTU

Site Address EAST Highway #38

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Caroline Kwan, DPRK - Rhymen, Jey.

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Progen evaluation - JST removed - 2 + TANKS installed
one old tank removed. - soil pile fenced off
w/ air venting machine on.

Findings, Accomplishments, and Results:

received soil data - appear clean.
But want BACK UP EPA/DC.
soil pile - covered w/ heavy vinyl - PVC.

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

received soil data report from soil Tech
2/27/90 -

Distribution:

Site Inspection Report

Inspection Date(s) 2/28/80

Site Name TOTU - ESSO

Site Address East 38 Highway

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Carolanne Kram, Greg Hyman

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Progress evaluation - Soil pile - 104 (e) follow-up -

Findings, Accomplishments, and Results:

*Soil pile covered - wood fenced in 3 feet high
Pail venting off - No observed release or
stains*

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Obtain soil disposal report from ESSO -

Distribution:

Site Inspection Report

Inspection Date(s)

2/27/90

Site Name

FVTV - TEXAS

Site Address

JOE 318 & 38 Highway

Persons Conducting Inspection:

(Identify EPA, State, Contractors, PRPs, Public, etc.)

Candace Kwan

DPOR - Greg Rhymen

Purpose of Inspection:

(Survey, data collection, field work, progress evaluation, etc.)

Progress evaluation - soil pile - reinspection

Findings, Accomplishments, and Results:

Follow-up and Recommendations:

(Correct problems, notification of appropriate EPA/State officials, PRPs, or contractor regarding problems, schedule for resolution, etc.)

Distribution: